light Shark series.

LS-Wing Software Change Log



1.0.6

IMPROVEMENTS

NEW: v1.0.6 becomes the base version, so when resetting the console it will revert to this software version.

For wings manufactured from September onwards. For those users who purchased the LS-Wing before September, please contact us and we will indicate the procedure.



1.0.5

NEW FEATURES

NEW: Generic UDP

NEW: Support for UDP

IMPROVEMENTS

NEW: The network configuration interface has been improved.

NEW: Performing a network reset also resets the network configuration of the built-in Node.

NEW: New bootmanager.



1.0.4

NEW FEATURES

NEW: Support for Generic OSC has been included.

IMPROVEMENTS

NEW: The network configuration interface has been improved.

NEW: Performing a network reset also resets the network configuration of the built-in Node.

NEW: New bootmanager.



